Air Monitoring Summary Tables

The table below summarizes monitoring data collected using a portable wireless remote monitoring system. All times in Eastern Standard Time (EST).

From: 09/07/23 12:00 am To: 09/07/23 11:59 pm

Offsite Monitors

Instrument	Analyte	ATSDR MRL 14-day Avg Reached?	14-day Avg Concentration Range Detected ^a		7-day Average	ATSDR 14-day MRL	
Catawba Headsta	Catawba Headstart						
Acrulog PPB	H_2S	No	0-0 ppb	0.00 ppb ^b	0.00 ppb	70 ppb	
Treetops							
Acrulog PPB	H_2S	No	0-0 ppb	0.00 ppb ^c	0.00 ppb	70 ppb	
Liberty Hill							
Acrulog PPB	H_2S	No	0 – 1 ppb	0.03 ppb ^d	0.18 ppb	70 ppb	
Riverchase Estat	es						
Acrulog PPB	H_2S	No	0 – 4 ppb	0.28 ppb ^e	0.18 ppb	70 ppb	
Millstone Creek							
Acrulog PPB	H_2S	No $0-1 \text{ ppb}$ $0.03 \text{ ppb}^{\text{ f}}$ 0.04		0.04 ppb	70 ppb		

^b The 24-hr average at Catawba Headstart is not represented by the full 24-hr period; a total of 8 30-minute averages are missing from the reported period due to the quarterly audit performed at this location.

Onsite Fenceline Monitors

Instrument	Analyte	30-min AEGL Reached?	Concentration Range Detected ^a	24-hr Average ^a	7-day Average	30-min AEGL	
Station 1							
TAPI Analyzer	H_2S	No	1 – 3 ppb	1.39 ppb	2.32 ppb	600 ppb	
Station 2							
TAPI Analyzer	H_2S	No	0 – 5 ppb	1.08 ppb	1.23 ppb	600 ppb	
Station 3							
TAPI Analyzer	H_2S	No	0 – 7 ppb 1.48 ppb ^g 1.08 ppb		600 ppb		

^a Based on 30-minute averages.

Notes:

ATSDR MRL Agency for Toxic Substances and Disease Registry Minimal Risk Level (MRL)

AEGL EPA Acute Exposure Guidelines Levels

H₂S Hydrogen Sulfide

TAPI Teledyne API H₂S Analyzer

hr Hour min Minute ppb Parts per billion

MRL Limit Limit defined as a 14-day average value.

^c The 24-hr average at Treetops is not represented by the full 24-hr period; a total of 7 30-minute averages are missing from the reported period due to the quarterly audit performed at this location.


^d The 24-hr average at Liberty Hill is not represented by the full 24-hr period; a total of 9 30-minute averages are missing from the reported period due to the quarterly audit performed at this location.

[°] The 24-hr average at Riverchase Estates is not represented by the full 24-hr period; a total of 9 30-minute averages are missing from the reported period due to the quarterly audit performed at this location.

^f The 24-hr average at Millstone Creek is not represented by the full 24-hr period; a total of 9 30-minute averages are missing from the reported period due to the quarterly audit performed at this location.

^g The 24-hr average at Station 3 is not represented by the full 24-hr period; a total of 11 30-minute averages are missing from the reported period due to the quarterly audit performed at this location.

Station 1 Wind Rose – Shows the direction the wind is coming from, the monitoring station being at the center of the rose.




Period H₂S Monitoring Hydrogen Sulfide Offsite Monitors

Below are graphs for offsite locations where hydrogen sulfide (H₂S) was detected during the current reporting period.


The five stand-alone H₂S monitoring stations correlate with five previous EPA's Viper monitoring system which includes areas to the north-northeast and south-southwest of the New-Indy Catawba Mill.

Winds were coming from variable directions throughout the day at 1 to 9 mph.


See wind rose diagram with aerial map figure for full wind data during this reporting period.




Treetops - 9/7/2023




Liberty Hill - 9/7/2023



Riverchase - 9/7/2023



Millstone Creek - 9/7/2023




Period H₂S Monitoring Hydrogen Sulfide Onsite Monitors


Below are graphs for onsite locations during the current reporting period.


Depending on wind direction, the H₂S measured at the onsite fence line locations may not exit the mill property at reported concentrations. Wind directions from offsite locations, blowing onto mill property, will disperse ambient concentrations to lower levels prior to exiting the plant site.

Winds were coming from variable directions throughout the day at 1 to 9 mph.

See wind rose diagram with aerial map figure for full wind data during this reporting period.







Submitted Fenceline H₂S and Met 30-minute Data

		Station 1			Station 2			Station 3	
30-Minute Avgs	H2S		let	H2S		let	H2S		let
_									
9/7/2023	30min Avg	30min	30min	30min Avg	30min	30min	30min Avg	30min	30min
_	H2S Conc.	Avg WS	Avg WD	H2S Conc.	Avg WS	Avg WD	H2S Conc.	Avg WS	Avg WD
Date / Time	ppb	mph	degrees	ppb	mph	degrees	ppb	mph	degrees
9/7/2023 0:30	AX	1.1	207	0.5	0.4	180	2.3	0.3	255
9/7/2023 1:00	1.4	1.8	189	AX	1.2	162	2.4	0.3	251
9/7/2023 1:30	1.3	1.7	164	0.7	0.9	158	AX	0.2	32
9/7/2023 2:00	1.2	1.9	155	0.6	0.7	126	6.6	0.2	113
9/7/2023 2:30	1.2	1.8	193	0.7	0.4	224	3.2	0.2	152
9/7/2023 3:00	1.2	1.6	195	0.6	0.7	184	1.4	0.4	221
9/7/2023 3:30	1.2	1.7	198	0.5	0.3	205	1.4	0.2	261
9/7/2023 4:00	1.2	1.6	195	0.5	0.5	154	1.8	0.2	201
9/7/2023 4:30	1.2	2.0	218	0.5	0.5	11	1.3	0.4	341
9/7/2023 5:00	1.2	1.4	164	0.8	0.3	52	1.5	0.2	97
9/7/2023 5:30	1.2	1.3	172	1.6	0.2	318	1.3	0.2	281
9/7/2023 6:00	1.2	1.9	185	1.4	0.2	317	1.0	0.2	359
9/7/2023 6:30	1.2	2.1	206	1.0	0.4	332	0.9	0.3	332
9/7/2023 7:00	1.2	2.2	189	3.1	0.7	26	1.1	0.4	15
9/7/2023 7:30	1.2	1.3	203	2.8	0.3	348	0.8	0.3	283
9/7/2023 8:00	1.2	0.7	190	1.8	0.5	337	AZ	0.3	278
9/7/2023 8:30	1.2	1.2	172	0.7	0.2	269	AZ	0.2	107
9/7/2023 9:00	1.2	1.3	226	0.7	0.5	264	AZ	0.4	87
9/7/2023 9:30	1.5	1.8	192	2.0	1.0	167	AZ	0.7	123
9/7/2023 10:00	2.8	1.1	329	2.9	0.8	262	AZ	0.7	79
9/7/2023 10:30	3.1	1.3	322	1.7	1.0	181	AZ	0.7	92
9/7/2023 11:00	2.2	1.2	341	0.7	1.0	82	AZ	1.2	36
9/7/2023 11:30	1.7	1.8	146	0.7	1.4	16	0.5	1.5	75
9/7/2023 12:00	1.1	2.9	153	0.7	1.7	350	0.2	2.0	27
9/7/2023 12:30	1.5	2.7	179	1.1	2.6	210	0.2	2.1	7
9/7/2023 13:00	1.5	2.0	184	1.3	2.0	214	0.7	1.7	91
9/7/2023 13:30	1.4	2.6	221	0.9	2.2	224	0.8	2.4	198
9/7/2023 14:00	1.3	1.9	208	0.9	2.2	232	0.5	2.5	191
9/7/2023 14:30	1.2	2.4	155	0.6	1.7	151	AZ	1.7	135
9/7/2023 15:00	1.1	2.6	163	0.6	1.9	156	AZ	1.6	144
9/7/2023 15:30	1.2	3.1	158	0.6	1.4	156	AZ	1.5	56
9/7/2023 16:00	1.3	2.9	150	0.5	1.5	138	AZ	2.0	167
9/7/2023 16:30	1.3	2.5	160	0.5	0.6	89	0.2	0.4	248
9/7/2023 17:00	1.3	4.3	249	0.7	2.2	285	0.2	0.4	352
9/7/2023 17:30	1.4	4.4	312	0.7	3.0	332	0.2	1.3	329
9/7/2023 17:30	1.3	8.8	203	0.2	4.7	216	2.1	3.8	239
9/7/2023 18:30	1.2	6.7	164	0.3	3.4	186	2.1	3.4	195
9/7/2023 19:00	1.3	4.5	104	0.2	1.4	39	0.2	2.0	90
9/7/2023 19:30	2.7	2.2	316	0.2	3.9	345	0.2	1.5	315
9/7/2023 19.30	1.2	3.2	185	0.6	2.2	112	0.2	2.0	161
9/7/2023 20:30		3.3	69	0.6		68	0.4		70
9/7/2023 20:30	1.5	4.0	146	0.7	2.0 0.8	72	0.6	2.3 1.0	148
	1.3								
9/7/2023 21:30	1.1	6.4	198	1.2	2.4	226	2.8	2.4	208
9/7/2023 22:00	1.1	4.8	203	1.2	2.5	205	5.6	2.4	210
9/7/2023 22:30	1.3	3.1	221	3.1	1.4	199	5.7	1.4	232
9/7/2023 23:00	1.3	2.4	278	4.5	1.4	278	2.5	0.7	303
9/7/2023 23:30	1.2	2.1	155	1.1	1.0	70	0.2	0.6	129
9/8/2023 0:00	1.1	1.5	162	1.3	0.8	102	0.2	0.6	178

AQS Null Data Codes					
Qualifier Code	Item Description				
AB	TECHNICIAN UNAVAILABLE				
AC	CONSTRUCTION/REPAIRS IN AREA				
AD	SHELTER STORM DAMAGE				
AE	SHELTER TEMPERATURE OUTSIDE LIMITS				
AI	INSUFFICIENT DATA (CAN'T CALCULATE)				
AM	MISCELLANEOUS VOID				
AN	MACHINE MALFUNCTION				
AO	BAD WEATHER				
AP	VANDALISM				
AS	POOR QUALITY ASSURANCE RESULTS				
AT	CALIBRATION				
AU	MONITORING WAIVED				
AV	POWER FAILURE (POWR)				
AW	WILDLIFE DAMAGE				
AX	PRECISION CHECK (PREC)				
AY	Q C CONTROL POINTS (ZERO/SPAN)				
AZ	Q C AUDIT (AUDT)				
BA	MAINTENANCE/ROUTINE REPAIRS				
BB	UNABLE TO REACH SITE				
BC	MULTI-POINT CALIBRATION				
BD	AUTO CALIBRATION				
BE	BUILDING/SITE REPAIR				
BF	PRECISION/ZERO/SPAN				
BJ	OPERATOR ERROR				
BK	SITE COMPUTER/DATA LOGGER DOWN				
EC	EXCEED CRITICAL CRITERIA				