

Public Notification of Previous Steam Stripper Activity

Notification Date: April 28, 2023

Explanation of Activity:

From time to time, the systems that support the steam stripper may stop functioning at the proper level due to interruptions (such as lightning strikes or increased conductivity) and need to be reset. These actions do not require the steam stripper to be opened or repaired. However, during such reset periods, the steam stripper may not process foul condensate. Instead, foul condensate is either stored or sent through the hard pipe. These reset times have occurred to date as outlined in the reset activity table below. In our continuing endeavor for transparency, we provide notice of these reset activities.

Reset Activity Table:

Date of Event:	Start Time and Total Duration:
01/03/23	00:00 – 120 minutes
01/29/23	18:50 – 210 minutes
02/02/23	13:50 - 690 minutes
02/06/23	11:40 – 50 minutes
02/16/23	15:00 – 40 minutes
03/02/23	09:50 – 70 minutes
03/18/23	08:00 – 100 minutes
04/02/23	21:10 – 70 minutes
04/07/23	09:20 – 30 minutes
04/10/23	04:40 – 50 minutes
04/10/23	13:50 – 60 minutes
04/17/23	20:00 – 40 minutes

Contact Information:

If you have any questions regarding this notice, New-Indy may be reached at: catawba.info@new-indycb.com