

Public Notification of Downtime Activity: COMPLETE June 29, 2024

In accordance with Paragraph 1 of Appendix "A" of the US Environmental Protection Agency ("EPA") Consent Decree dated November 16, 2022 (Civil No. 0:21-cv-02053-SAL), and New-Indy Catawba LLC's ("New-Indy") Public Notification Plan dated May 17, 2021, New-Indy presents the following Public Notification.

Description of Activity	:		
Rupture disk sensor failure.			
PLANNED	UNPLANNED 🖾		
Purpose of Activity:			
Rupture disk 37ZA025 indicated that the disk was blown causing a downtime event. The disk was removed and inspected for cause of failure. It was discovered that the sensor showing the status of the disk had failed. The disk was replaced, and the stripper was brought back online. Activity Status:			
Event 1	June 29, 2024 at 10:47 am to 12:21pm, 1 hour 34 minutes duration		
ORP Monitoring & Controls	Functioning 🛚	Excursions: No Yes	N/A
Current Status	Work is Complete ⊠		Stripper is Online 🛛

Contact Information:

New-Indy may be reached at catawbainfo@new-indy.com concerning this activity.